
















**ORDINANCES**  
**History of Code Adoptions in Arlington**  
(07/26/18)

BUILDING CODE	MECHANICAL CODE	ELECTRICAL CODE	PLUMBING CODE
<b>60-61 SBC</b> 6/20/61	<b>LOCAL CODE</b> 1956	<b>56 NEC</b> 3/21/61	<b>LOCAL CODE</b> 1956
<b>65 SBC</b> 7/20/68		<b>65 NEC</b> 10/3/67	
<b>70 UBC</b> 5/25/71	<b>70 UMC</b>	<b>68 NEC</b> 1/7/69	
<b>73 UBC</b> 12/10/74	<b>76 UMC</b> 10/7/78	<b>71 NEC</b> 4/25/72	<b>70 UPC</b> 12/10/74
<b>79 UBC</b> 11/3/81	<b>79 UMC</b> 12/29/81	<b>78 NEC</b> 1/2/79	
<b>82 UBC</b> 12/21/82		<b>81 NEC</b> 1/19/82	
<b>85 UBC</b> 10/15/85	<b>85 UMC</b> 3/11/86	<b>84 NEC</b> 3/11/86	<b>85 UPC</b> 3/11/86
<b>88 UBC</b> 6/27/89		<b>87 NEC</b> 2/23/88	
		<b>90 NEC</b> 10/01/91	
<b>91 UBC</b> 1/20/94	<b>91 UMC</b> 11/07/93	<b>93 NEC</b> 9/06/94	<b>91 UPC</b> 10/26/93
<b>94 UBC</b> 7/19/96	<b>94 UMC</b> 7/2/96	<b>96 NEC</b> 1/31/97	
<b>97 UBC</b> 11/10/98		<b>99 NEC</b> 10/1/00	<b>97 IPC</b> 4/30/99
	<b>2000 IMC</b>	<b>2002 NEC</b>	
<b>2000/IBC/IRC</b> 02/21/02	4/10/03	09/01/04	<b>2000 IPC/IFGC</b> 4/10/03
<b>2003/IBC/IRC/IECC</b> 11/01/05			
	<b>2003 IMC</b> 11/01/05		<b>2003 IPC</b> 11/01/05
<b>2009 IBC/IRC/IECC</b> 05/24/12	<b>2009 IMC</b> 05/24/12	<b>2008 NEC</b> 05/24/12	<b>2009 IPC/IFGC</b> 05/24/12
<b>2015 IBC/IRC/IECC</b> 05/14/18	<b>2015 IMC</b> 05/14/18	<b>2017 NEC</b> 05/14/18	<b>2015 IPC/IFGC</b> 05/14/18